




d_{nom}	Pod gwint	d	D	s
3,2	M3	3,2	7	0,5
4,3	M4	4,3	10	0,8
5,5	M5	5,5	10	1,0
6,6	M6	6,6	12	1,6
9,0	M8	9,0	16	1,6
11	M10	11	20	2,0
13,5	M12	13,5	24	2,5
15,5	M14	15,5	28	2,5
17,5	M16	17,5	30	3,0
20	M18	20	34	3,0
22	M20	22	37	3,0
26	M24	26	44	4,0
33	M30	33	56	4,0

