



<b>d<sub>nom</sub></b>	<b>Pod. gwint</b>	<b>d<sub>1</sub></b>	<b>d<sub>2</sub></b>	<b>h<sub>min</sub></b>	<b>h<sub>max</sub></b>	<b>s</b>
<b>4</b>	<b>M4</b>	<b>4,3</b>	<b>7</b>	<b>0,59</b>	<b>1,0</b>	<b>0,5</b>
<b>6</b>	<b>M6</b>	<b>6,4</b>	<b>10</b>	<b>0,82</b>	<b>1,2</b>	<b>0,7</b>
<b>8</b>	<b>M8</b>	<b>8,4</b>	<b>13</b>	<b>0,98</b>	<b>1,4</b>	<b>0,8</b>
<b>10</b>	<b>M10</b>	<b>10,5</b>	<b>16</b>	<b>1,21</b>	<b>1,6</b>	<b>1</b>
<b>12</b>	<b>M12</b>	<b>13</b>	<b>18</b>	<b>1,31</b>	<b>1,7</b>	<b>1,1</b>
<b>16</b>	<b>M16</b>	<b>17</b>	<b>24</b>	<b>1,63</b>	<b>2,1</b>	<b>1,3</b>
<b>20</b>	<b>M20</b>	<b>21</b>	<b>30</b>	<b>1,94</b>	<b>2,5</b>	<b>1,5</b>



**Podkładka sprężysta ząbkowana Schnorr AN 131, stal sprężysta, czerniona.**