



d_{nom}	Pod gwint	d_1	d_2	h_{nom}
5,5	M5	5,5	18	2
6,6	M6	6,6	22	2
9	M8	9	28	3
11	M10	11	34	3
13,5	M12	13,5	44	4
18	M16	18	56	5
22	M20	22	72	6
24	M22	24	80	6

